






SHIELD ADAPTERS, GROUNDING KITS AND JACKET SEALS

Elastimold elbows, splices and terminators are designed for application on XLP, EPR and other solid dielectric insulated power cables. As shown in the diagram below, a variety of shielding and jacketing methods are available for these types of cables. In some cases, the use of cable shield adapters, grounding kits and/or jacket seals are required in order to properly install Elastimold components. Refer to the diagram below for recommendations, selection and use of adapters, grounding kits and jacket seals.

CABLE ENTRANCE DETAIL



CABLE SHIELD ADAPTERS			
Cable Insulation Dia.	10TL inches	20MA inches	21MA inches
min.	.495	.575	.575
max.	1.755	1.755	1.755

JACKET SEALS		
Jacket O.D.	200ECS inches	600ECS inches
min.	.80	1.28
max.	1.50	2.30